





CDU-L with DOUBLE EVAPORATOR CIRCUIT

CDU-L Service valves



Double Circuit Evaporator CGC312F8ED 0241

- The CO2 piping must be connected as per the above drawing (in opposite way of air Flow)